


SMR Module Plug & Wiring Diagram Anderson Powerpole Connectors



Tap splices to terminal block on module cross brace.
All connections to module will be made at terminal block.
Absolutely no other connections will be made to through wiring.

Not to scale

Drawing is the underside of a module
Rails are numbered from Front to Back (1 thru6)

Track feeder wires
20 gauge solid wire